

Haddenham to Thame Community Path – Via Scotsgrove Mill



1



2



3



4



5



6



7



8



9



10



11



12



13



14



15



16



17



18



19

- 01\_unsurfaced bridleway Moorend Lane.JPG
- 02\_Moorend Lane Farm.JPG
- 03\_unsurfaced bridleway\_stile to left onto fpath.JPG
- 04\_unsurfaced bridleway.JPG
- 05\_Gate into field\_not definitive fpath.JPG
- 06\_route along hedgeline edge of field.JPG
- 07\_bridge.JPG
- 08\_open meadow\_existing fpath.JPG
- 09\_broken stile onto BCC fpath and bridge.JPG
- 10\_broken stile and bridge.JPG
- 11\_fpath HAD11.1 60meters.JPG
- 12\_fpath HAD11.1 with nocycling sign.JPG
- 13\_fpath past scotsgrove mill.JPG
- 14\_bridleway HAD1.1.JPG
- 15\_bridleway.JPG
- 16\_bridleway.JPG
- 17\_right turn to fpath HAD.18.2.JPG
- 18\_bridleway HAD1.2 ends at Station Rd.JPG
- 19\_from Station Rd.Bway up road on right.JPG

## Haddenham to Thame Community Path – Option B Via Tythrop



20



21



22



23



24



25



26



27



28



29



30



31



32



33



34



35



36



37



38



39



40



41



42



43

20\_Footpath.JPG  
21\_narrow fpath north of rail line.JPG  
22\_kissing gate.JPG  
23\_looking back twd kissing gate.JPG  
24\_fpath under rail line.JPG  
25\_HADD17.1.JPG  
26\_HAD17.1 Kissing gate.JPG  
27\_fpath.JPG  
28\_bridge at KIN1.1 jw KIN2.1.JPG  
29\_KIN1.1 cross crop field to stile.JPG  
30\_stile into cow field.JPG  
31\_KIN1.1 cow field.JPG  
32\_stile from cow to arable.JPG  
33\_field edge arable.JPG  
34\_KIN1.1 arable.JPG  
35\_stile\_from end of crop to fencing storage.JPG  
36\_through fencing storage yard.JPG  
37\_leaving yard.JPG  
38\_stile in field gate.JPG  
39\_stile to bridleway.JPG  
40\_stile to bridleway.JPG  
41\_stile to bridleway.JPG  
43\_existing bridleway.JPG